

5 References and supporting documents

- WRAC - RA134 Floor treatment
- CB-SAH-STD-0045 Mine roadway specification
- CB-SSE-SOP-0002 Check and examine work areas
- CB-SSE-SOP-0015 Work on or near product stockpiles or waste dumps
- CB-SSE-SOP-0016 Working on spoil dumps and near excavated faces and discharging loads from fixed and mobile equipment
- CB-SSE-SOP-0018 Raw coal stockpiles
- CB-SAH-WIS-0015 Work at height
- CB-SSE-SOP-0040 Working near a body of water
- CB-TSE-MNP-0001 Geotechnical hazard management plan (GHMP)
- CB-TSE-TRP-0005 TARP for Work area inspections – Dumps and stockpiles
- CB-TSE-TRP-0006 TARP for Dump operations – Dumping of tertiary sediment material
- CB-TSE-TRP-0007 TARP for Dump operations – Dumping of weathered material
- CB-TSE-TRP-0008 TARP for Dump operations – Dumping of fresh rock

6 Abbreviations and definitions

Term	Definition
Document owner	Person taking accountability for the technical content of documentation created.
FOPS	Falling object protection system
OCE	Open Cut Examiner
PEA PCI	Peabody Energy Australia PCI Pty Ltd
Shall / must	Indicates that a statement is mandatory
Should	Indicates a recommendation.
SOP	Standard Operating Procedure
SSE	Site Senior Executive